

ABSTRACT

The method comprises the steps of: applying an isothermal transformation heat treatment to a wire material having a nonmetallic inclusion controlled; applying a lubrication film after acid washing; carrying out scalping
5 after which softening a work hardened layer produced on a surface layer at the time of scalping by annealing and carrying out wire drawing, and then carrying out an oil temper treatment.